MATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS AND RELATED MATERIALS OF CAPPUT (Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP. August 1977

Section I

MANUFACTURER'S NAME

Koppers Company, Inc.

STREET ADDRESS

5431 District Blvd

CITY. STATE. AND ZIP CODE Pernon, CA 90040

EMERGENCY TELEPHONE NO.

213 - 726-8666

PRODUCT CLASS

Vinyl Texture

MANUFACTURERS CODE IDENTIFICATION

L-770-66

455 Red Tone Moly Orange

TRADE NAME

Section II — HAZARDOUS INGREDIENTS

INGREDIENT	PERCENT	PPM	LV ma/M³	LEL	VAPOR PRESSURE
Lead AS Pb in Moly Orange Chromium AS Cr in Moly Orange Methyl Ethyl Ketone Cellosolve Solvent (may be absorbed via skin) Methyl Isobutyl Ketone Vinyl Chloride Vinyl Acetate Trepolymer Proplene Oxide Isophrene N-Butanol	15.5 3.3 33.5 1.7 11.4 14.2 .16 .28 1.86	200 200 100 100 25 100	740 409 15 240 141 303	1.8 2.6 1.3 - 2.1 0.8 1.4	1mm/9,73°C 1mm/16.16°C 71.2mm/20°C 3.8mm/20°C 16mm/20°C 400mm/17,8°C 1mm/38°C 5,5mm/20°C
SO 1200 Solvent	7,00	150	,	1,2	36mm/100°F

Section III — PHYSICAL DATA

BOILING RANGE

175-244

VAPOR DENSITY

X HEAVIER

LIGHTER, THAN AIR

EVAPORATION RATE

FASTER

X SLOWER, THAN ETHER

PERCENT VOLATILE

WEIGHT PER 80%

 $9.5 \pm .1$

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

Flammable - Red Label

FLASH POINT

23°F TCC

1.2 LEL

CO2, Dry chemical or foam **EXTINGUISHING MEDIA**

unusual fire and explosion hazaros Explosive vapor mixture may be formed between upper and lower explosive limits. Do not use welding or cutting torch on or near drum (even empty).

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water

Section V — HEALTH HAZARD DATA				
THRESHOLD LIMIT VALUE N/A				
EFFECTS OF OVEREXPOSURE				
Headache, nausea, moderately irritating to eyes and skin				
EMERGENCY AND FIRST AID PROCEDURES				
Remove victims from vapors - restore breathing if necessary. Remove from skin with soap and water.				
Flush eyes with water.				
Cotion VI DEACTIVITY DATA				
Section VI — REACTIVITY DATA				
STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid)				
HAZARDOUS DECOMPOSITION PRODUCTS CO, CO2, aldehydes, and other organics, lead oxide				
chromic oxide, hydrogen chloride				
HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR				
CONDITIONS TO AVOID .				
Section VII — SPILL OR LEAK PROCEDURES				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED				
Remove source of ignition. Apply sawdust or other absorbent material.				
Keep material from spreading.				
Put in metal container and seal for disposal				
Section VIII — SPECIAL PROTECTION INFORMATION				
RESPIRATORY PROTECTION Devices				
For confined areas use Bureau of Mines Respiratory Device				
Approval 25 B-13 BM2304 Face Piece				
BM2304 Cartridge				
BM2313 Filters				
VENTILATION BM2313 Filter Clips				
Ventilation should be adequate to keep lower level below LEL				
PROTECTIVE GLOVES Rubber				
EYE PROTECTION Safety				
OTHER PROTECTIVE EQUIPMENT Rubber soles must be worn (no static electricity)				
Section IX — SPECIAL PRECAUTIONS				
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING				
Flammable store away from open flame and high heat				
OTHER PRECAUTIONS Do not take internally - avoid prolonged contact				
with skin				